





Model # : Y-H936A
Assembly Instruction






A × 4




M8×20 mm

B × 12




M8×50 mm

C × 4




M8×70 mm

D × 2




M8×120 mm

E × 4




M8/14 mm

F × 26




Ø8/Ø22 mm

G × 1




14 mm

H × 1




6 mm

J × 8




Ø12/Ø24 mm


K × 8




Ø25×3 mm




Box 1/4:




1465×490×200mm




1470×690×95mm




1460×700×180mm




740×430×210mm




Ø50×Ø32×150mm




125×125×150mm



Ø30×145mm



Box 2/4:




890×490×150mm




890×490×150mm

Box 3/4:




1540×1110×95mm




1560×1130×180mm


Box 4/4:



1105×490×200mm




1120×430×210mm







430×430×150mm





1






2










3

<p>B × 5</p>  <p>M8×50 mm</p>	<p>C × 2</p>  <p>M8×70 mm</p>	<p>F × 7</p>  <p>Ø8/Ø22 mm</p>	<p>H × 1</p>  <p>6 mm</p>	
--	--	---	---	--











4

<p>B × 5</p>  <p>M8×50 mm</p>	<p>C × 2</p>  <p>M8×70 mm</p>	<p>F × 7</p>  <p>Ø8/Ø22 mm</p>	<p>H × 1</p>  <p>6 mm</p>	
--	--	---	---	--








5

$B \times 2$  M8x50 mm	$D \times 2$  M8x120 mm	$E \times 4$  M8/14 mm	$F \times 8$  Ø8/Ø22 mm	$G \times 1$  14 mm	$H \times 1$  6 mm
---	--	---	---	--	---





6

$A \times 4$  M8x20 mm	$F \times 4$  Ø8/Ø22 mm	$H \times 1$  6 mm	
---	--	---	--





7

J x 8	
	
Ø12/Ø24 mm	




8


K x 8	
	
Ø25x3 mm	







9






10










11

B × 5  M8×50 mm	C × 2  M8×70 mm	F × 7  Ø8/Ø22 mm	H × 1  6 mm	
--	--	---	---	--










12

B × 5  M8×50 mm	C × 2  M8×70 mm	F × 7  Ø8/Ø22 mm	H × 1  6 mm	
--	--	---	---	--







13

$B \times 2$  M8x50 mm	$D \times 2$  M8x120 mm	$E \times 4$  M8/14 mm	$F \times 8$  Ø8/Ø22 mm	$G \times 1$  14 mm	$H \times 1$  6 mm
---	--	---	---	--	---




14

$A \times 4$  M8x20 mm	$F \times 4$  Ø8/Ø22 mm	$H \times 1$  6 mm	
---	--	---	--




15

<p>J × 8</p>  <p>Ø12/Ø24 mm</p>	
--	--




16

<p>K × 8</p>  <p>Ø25×3 mm</p>	
--	--



17



18

